EH&S Presents...

LSR Quarterly Meeting

February 15, 2011



Agenda

- Introductions
- Shipping GMMOs
- Lab Inspection Update
 - Upcoming Inspections
 - 2010 Inspection Overview
- Fire Safety
- Fire Extinguisher Training

Shipping Genetically Modified Micro-Organisms

- New Definition for 2011 (IATA DGR):
 - "... genetic material has been purposely altered through genetic engineering in a way that does not occur naturally"
- What to do:
 - See hand out
 - Put sticker on box



Lab Inspections Update Winter 2011

- Physics & Engineering almost complete
- Environmental Studies February
- Anthropology February
- Chemistry March



Deficiency Correction Notice - Laboratory Safety Survey




UCSC Environmental Health and Safety Programs

Survey Date: June 16, 2002

Industrial Hygiene Services

Buddy Morris						EH&S Trailer	
Please date, initial, and return this page to EH&S as soon as all items are corrected or by June 23, 2002.							
	Inspection Details:	Severity Risk Rank:		Correct by Target Date	: Corrected?	Corrected: (date/initial)	
Red	cords and Documentation - IIPP						
Lal	Group						
1.	Safety training required for your operations has not been provided to all employees.	High	5	7/4/2002	No	to .	
Lab	Standard Compliance						
Lal	o Group		200				
2.	Chemical wastes are not properly managed in the lab.	High	5	6/23/2002	No		
3.	Chemical wastes are not properly managed in the lab.	High	5	6/23/2002	No		
4.	Flammable chemicals are stored close to sources of ignition.	High	5	7/6/2002	No		
5.	Flammable chemicals are stored close to sources of ignition.	High	5	7/7/2002	No		
6.	Chemicals which are potentially very hazardous (explosive, reactive, carcinogenic, etc.) are not being properly managed.	High	5	7/6/2002	No		
7.	Facilities Inappropriate for Work Activities	Med	14	7/16/2002	No		
8.	Facilities Inappropriate for Work Activities	Med	14	7/16/2002	No		
9.	Facilities Inappropriate for Work Activities	Med	14	7/16/2002	No	7.0	
10.	Old chemicals are being stored.	Med	14	7/15/2002	No		
11.	Excess quantities of flammable liquids are stored in the lab.	Med	14	7/15/2002	No	33	
12.	Glass waste containers are not properly managed in the Lab.	Med	14	7/2/2002	No	n	
13.	Glass Trash Containers not used.	Med	14	7/2/2002	No		
14.	Switch cover is missing.	Low	30	8/1/2002	No		
15.	An electrical cord is not properly channelled.	Low	30	8/1/2002	No		
16.	The boiler permit on the autoclave is expired.	Low	3 0	8/1/2002	No		
17.	Shelves do not have restraints to prevent items from falling.	Low	30	8/1/2002	No	- 70	
18.	Equipment such as book shelves, cabinets, or storage shelves	s Low	30	8/1/2002	No		


2010 Lab Inspection Summary



Equipment Issues

- Immersion circulators in plexi tanks
 w/inadequate overtemp/drybath protection
- Hotplates uncontrolled heating
- Wrong fuse need exact replacement, not just same V
- Partially inserted power plugs
- Lab bench clutter
- New eqpt field wiring check ampacity ratings (ice machine)
- Imported eqpt designed for different V supply


2009 Cyclohexane Fire



2004 Sinsheimer Fire



2003 Thimann Hot Plate Fire



2003 Thimann Raney Nickel Fire



2003 Thimann Alcohol Fire



2002 Sinsheimer Fire





2002 Sinsheimer Fire, cont'd



2002 Sinsheimer Fire, cont'd




2002 Sinsheimer Fire, cont'd



1999 Sinsheimer Fire



1999 Sinsheimer Fire





Fire Safety



Fire Safety

 UCSC Fire & Electrical Safety Self Inspection Form



UCSC Fire Department



